


VR4030CS-AL Vapor Hose Couplers

4" x 3" with poppet

Bill of Materials

Item #	Description	Part #	Qty
1	body	---	1
2	cam arm and ring	300-HR-BR	2
3	cam pin	L519-19	2
4	Buna coupler gasket	400-G-BU	1
5	probe	VR6000-7	1
6	FKM valve O-ring	O-RING-AS-334	1
7	spring	SPRG/L4238	1
8	bushing	VR6000-3	1
9	valve	VR4030CS-1	1
10	valve plate	110226	1



Repair Kit


Part #	Description	Includes Item #
VAC4030RK	replacement cam arms, rings, pins, coupler gasket and valve O-ring	2, 3, 4, 6

4030-CVR-AL Vapor Hose Couplers

4" x 3" without poppet

Bill of Materials

Item #	Description	Part #	Qty
1	body	---	1
2	cam arm and ring	300-HR-BR	2
3	cam arm pin	L519-19	2
4	Buna coupler gasket	400-G-BU	1
5	probe	VR4030CS-3	1




VRC3000AL Vapor Hose Couplers

3" x 3"

Bill of Materials

Item #	Description	Part #	Qty
1	body	---	1
2	probe	L4217	1
3	cam arm and ring	300-HR-BR	2
4	Buna coupler gasket	300-G-BU	1
5	cam arm pin	325-P	2



Product instruction sheets and technical data can be viewed on our website at dixongroupcanada.com by selecting the 'Resources' menu.